VINYL INSTALLATION

Step 6. Hold lettering away from surface with one hand & allow adhesive to touch only as pressure is applied with a squeegee. Start at the top center of the lettering working down and outward to each edge of mask. Then go back to the top and work down again.



Step 7. Peel back the application tape slowly, making sure all of the lettering or decal is stuck to the surface.





Step 8. Inspect the decal for air bubbles or wrinkles. Poke any trapped air with a pin and press with fingers. Stand back and your instullation is complete.



